


ALWAYS READY ROCKETRY

30751 Tremont Drive
Wesley Chapel, FL 33543
813-484-1298
arrsales@cox.net

Good morning Blue Tube Dealers,

It has been recently brought to my attention that a situation exists in regards to a warping issue for Blue Tube. Certain long aspect ratio rocket designs, when sitting in direct sunlight under high heat and high humidity will bow towards the hot side. It will return to shape on its own once it is cooled, but will obviously fly erratically if the rocket is flown shown in "after.jpg". This does not affect short or normal aspect ratio rockets, does not affect the boosters, does not affect large diameter airframes, and does not affect the electronics bays, motor mount tubes or anything else. It only appears to affect the space between the top of the electronics bay and the nosecone where it is un-reinforced and there are no centering rings, inside tubes or couplers. There have obviously been many Blue Tube based rockets have flown perfectly and retain their shape; it just appears worst with tall skinny rockets exposed to very hot and humid climates. Existing rocket designs can be fixed simply by double walling the affected area with an inexpensive phenolic coupler epoxied into place. The issue has been brought to the attention of the manufacturer, and the problem has been analyzed and an improvement is pending. All backorders and stock reorders are on hold, and will not be refilled from Tampa stock, but will be refilled from a new factory run utilizing a new technique in August. Please feel free to contact me if you have any questions and thank you to Carey Huff from Huff Performance for bringing this issue to my attention. Please see attached photos.

Sincerely,

A handwritten signature in black ink that reads "Randall J. Ejma". The signature is written in a cursive, flowing style.

Randall J. Ejma
Always Ready Rocketry



Phoenix
Missile
Works

3

